



CARTWRIGHT'S HILL SUBDIVISION

City of Wagga Wagga

Landscape Stability



Erosion/Instability Hazard	Major Limitations	Capability	Code
Low	Nil	EBC	A-0
Moderate	Erodible soil	EBC	B-3
Moderate	Slope/erodible soil	Residential	B-1,3
High	Slope/erodible soil	Low density residential	C-1,3
Very high	Slope/erodible soil	Reserve	D-1,3
Very high	Flood plain	Reserve	D-2
Very high	Slope/drainage/erodible soil	Reserve	D-1,2,3
Extreme	Drainage/erodible soil	No development	E-2,3

* EBC - Extensive Building Complexes